

## Industrial HiVision v06.0.08 released

2018-02-19 - - Software Products

Fixes in version 06.0.08

- After restarting the Industrial HiVision service, devices in subdomains with a leased license could no longer request SNMP data.
- SNMP Timeouts occur with HiOS devices when SHA authentication and AES encryption is used.
- Device Configuration function does not work with HiOS v7.0.

Related Content

- [Industrial\\_HiVision\\_v06\\_0\\_08\\_Linux.zip](#)
- [Industrial\\_HiVision\\_v06\\_0\\_08\\_Windows.zip](#)
- [HAC\\_Issue-List\\_2018-02-16.pdf](#)