Since the update to v09.1.03, the web interface can no longer be opened in HiView

Christoph Strauss - 2022-01-10 - Classic Switches

Classic Switch firmware version 09.1.03 requires HiView version 03.2.02 or newer.