BAT 867-F restart wlan :too many tx timeout at 5G-high

Alex Liu - 2024-09-19 - BAT, WLC (HiLCOS)

1.Topology

a.There are 8 cranes

b.Every crane has 3 CCTV(totally 2Mbits) and 1 PLC

-
  2.Installation

a.Installed a 867-F on the crane as a "Station"

b.Installed a 867-F on the grond as a "Ap",the ground AP is equal altitude to the Station .

c.5.8Ghz antennas face to face .

3.Configuration

- a. firmware :10.34.5895-RU4 / 14.02.2023

- b. radio

Tags

BAT

BAT867-F