

HiOS 08.7.04 released

2021-11-22 - Christoph Strauss - Switches and Router

Bugfix for SFP issue, see <https://hirschmann-support.belden.com/news/posts/119>

Software Release 08.7.04

Bugfixes (see Issue List)

Ähnliche Inhalte

- [Web_BRS_08704.zip](#)
- [Web_DRAGON_08704.zip](#)
- [Web_GRS_08704.zip](#)
- [Web_MSP_08704.zip](#)
- [Web_OCTOPUS_08704.zip](#)
- [Web_RDD_08704.zip](#)
- [Web_RSP-2A_3S_08704.zip](#)
- [Web_RSPE_08704.zip](#)
- [HAC_Issue-List_2021-11-24.pdf](#)