

## Classic Switch v09.1.03 released

2020-11-13 - Christoph Strauss - Switches and Router

Software Release 09.1.03

-----

Bugfixes (see issuelist)

Note: If you are using HiView, a newer HiView version 03.2.02 is required for this firmware version.

HiView 03.2.02 will be released shortly. A beta version can be found here:

<https://hirschmann-support.belden.com/downloads/files/3044>

### Related Content

- [HAC\\_Issue-List\\_2020-11-10.pdf](#)
- [Web\\_m4002L2P\\_09103.zip](#)
- [Web\\_m4002L3E\\_09103.zip](#)
- [Web\\_m4002L3P\\_09103.zip](#)
- [Web\\_m4002xgL2P\\_09103.zip](#)
- [Web\\_m4002xgL3E\\_09103.zip](#)
- [Web\\_m4002xgL3P\\_09103.zip](#)
- [Web\\_MACH100\\_09103.zip](#)
- [Web\\_MACH100GE\\_09103.zip](#)
- [Web\\_MACH1000GE\\_09103.zip](#)
- [Web\\_MAR1000\\_09103.zip](#)
- [Web\\_MICE\\_09103.zip](#)
- [Web\\_Octopus\\_09103.zip](#)
- [Web\\_OpenRail\\_09103.zip](#)
- [Web\\_pmL2P\\_09103.zip](#)
- [Web\\_pmL3E\\_09103.zip](#)
- [Web\\_pmL3P\\_09103.zip](#)
- [Web\\_RSR\\_09103.zip](#)