

HiOS v08.4.01 released

2020-09-11 - - Switches and Router

Software Release 08.4.01

Bugfixes (see Issue List)

New Functions:

- Maximum number of configurable static routes increased from 512 to 1280.
- BOOTP/DHCP options (DHCP client) can be switched off.
- Display differences to default configuration in the graphical user interface.
- New parameter "index" in the CLI for adding and deleting ACL rules.

Related Content

- [HAC_Issue-List_2020-09-09.pdf](#)
- [Web_BRS_08401.zip](#)
- [Web_DRAGON_08401.zip](#)
- [Web_GRS_08401.zip](#)
- [Web_MSP_08401.zip](#)
- [Web_RDD_08401.zip](#)
- [Web_RSP-2A_3S_08401.zip](#)
- [Web_RSPE_08401.zip](#)