



Base de conocimiento > Products > Are Hirschmann products affected by vulnerability VU#793496?

---

## Are Hirschmann products affected by vulnerability VU#793496?

Christoph Wrobel - 2024-09-19 - Products

**TO BE PUBLISHED WITH FIRST REQUEST**

The following Hirschmann products are affected by the vulnerability described in VU#793496 (<http://www.kb.cert.org/vuls/id/793496>):

RS, RSR, RSB, MACH100, MACH1000, MACH4000, MS, OCTOPUS, RSP, RSPE, RSPS, RSPL, MSP, EES, EESX, GRS, OS, RED, HiSecOS EAGLE20/30

We have rated this issue as an issue in the OSPF protocol itself with moderate security impact. This issue is not currently planned to be addressed in future updates.“