


## BAT 867-F restart wlan :too many tx timeout at 5G-high

Alex Liu - 2024-09-19 - BAT, WLC (HiLCOS)

### 1.Topology

a. There are 8 cranes

b. Every crane has 3 CCTV(totally 2Mbits) and 1 PLC



### 2.Installation

a. Installed a 867-F on the crane as a "Station"

b. Installed a 867-F on the ground as a "Ap", the ground AP is equal altitude to the Station .

c. 5.8Ghz antennas face to face .



### 3.Configuration

- a. firmware :10.34.5895-RU4 / 14.02.2023
- b. radio

Etiquetas

BAT

BAT867-F