

## Industrial HiVision v07.0.04 released

2018-02-19 - - Software Products

New features in version 07.0.04

- MultiConfig™ Dialog enhanced:
  - HSR Dialog (added: MTU, Speed)

Fixes in version 07.0.04

- Devices with a leased license in subdomains no longer could request SNMP data after restarting the service.
- SNMP Timeouts occur with HiOS devices when SHA authentication and AES encryption is used.
- MultiConfig™ - Basics - Software: In http(s)-Software-Update dialog, no file selection on local machine available using remote GUI.
- Device Configuration function does not work with HiOS v7.0.
- After importing a project from Industrial HiVision v6 to Industrial HiVision v7, redundant connections are not displayed correctly.
- Changes of the status for the property "System Start" are not detected by Industrial HiVision.

Contenuti correlati

- [Industrial HiVision 07.0.04 Linux](#)
- [Industrial HiVision 07.0.04 Windows](#)
- [Issue List](#)