

HiOS 08.9.00 released

2021-10-29 - - Switches and Router

1. Limitations of the release GRS106 08.9.00

=====

USB-C: The Out-of-Band management interface exclusively supports CLI access via terminal emulation.

2. Supported Hardware

=====

This platform software release 08.9.00 is released exclusively for the following hardware:

HiOS-GRS-08900.bin:

- GRS105-6F8F16T (Since SW 08.9.00)
- GRS105-6F8T16T (Since SW 08.9.00)
- GRS106-6F8F16T (Since SW 08.9.00)
- GRS106-6F8T16T (Since SW 08.9.00)

Supported Software Level:

- 2S (GRS...2S, GRS...2A)
- 2A (GRS...2A)

For information on supported accessories, refer to the "User Manual Installation". You will find the manuals under "<https://www.doc.hirschmann.com>".

3. History of Changes

=====

Software Release 08.9.00

First Version

New Functions:

- Humidity Sensor
- Responsive GUI

関連コンテンツ

- [HAC_Issue-List_2021-10-15.pdf](#)
- [Web_GRS_08900.zip](#)