

## HiOS v08.4.01 released

2020-09-11 - Christoph Strauss - Switches and Router

Software Release 08.4.01

-----  
Bugfixes (see Issue List)

New Functions:

- Maximum number of configurable static routes increased from 512 to 1280.
- BOOTP/DHCP options (DHCP client) can be switched off.
- Display differences to default configuration in the graphical user interface.
- New parameter "index" in the CLI for adding and deleting ACL rules.

関連コンテンツ

- [HAC\\_Issue-List\\_2020-09-09.pdf](#)
- [Web\\_BRS\\_08401.zip](#)
- [Web\\_DRAGON\\_08401.zip](#)
- [Web\\_GRS\\_08401.zip](#)
- [Web\\_MSP\\_08401.zip](#)
- [Web\\_RDD\\_08401.zip](#)
- [Web\\_RSP-2A\\_3S\\_08401.zip](#)
- [Web\\_RSPE\\_08401.zip](#)