

HiSecOS v04.1.00 released

2021-04-20 - - Firewalls

Software Release 04.1.00

New Feature supported:

IEC104 Enforcer

Security Fix:

None

Open points and decisions:

- FDB: After adding static mac address to interface-1, same mac is getting learned to other interface-2 while traffic is send with same mac as source mac on interface-2
- No support of copper SFP in device, it might work with hot plug in and port goes down after reboot
- Eagle web become unresponsive, once web remain open for more than a day
- Vlan tagged packet not getting filtered by I2 filtering if matched on vlan interface with untagged egress port
- After creating around 1000 L2 filter rule via CLI, web of L2 filter rule gives error to contact to manufacturer

関連コンテンツ

- [HAC_Issue-List_2021-04-18.pdf](#)
- [HiSecOS-04100-EAGLE3.zip](#)
- [HiSecOS-04100-EAGLE40.zip](#)
- [HiSecOS-04100-EAGLE4007.zip](#)