

HiOS 10.2.00 has been released

2024-12-19 - - Switches and Router

Software Release 10.2.00

Bugfixes (see Issue List)

New Functions:

Software Level 2A:

- TACACS+ client

- sFlow

Conteúdo relacionado

- [Web_BRS_10200](#)
- [Web_GRS_10200](#)
- [HAC_Issue_List_2024-12-19](#)