

## Industrial HiVision 08.5.00 released

2024-03-21 - Christoph Strauss - Software Products

### Issues fixed

- You can find the known problems, workarounds, fixes and java-vulnerabilities corrected in the issue list.

### FAQ (Frequently Asked Question)

- You can find answers to common question in the FAQ page. The FAQ page is located using the following link  
<https://hirschmann-support.belden.com/en/kb/industrial-hivision>

### New features in version 08.5.00

- New Devices
  - Hirschmann IT DAP847

### Additions to the manual in version 08.5.00

- Hirschmann IT Family
  - MTS Family: In the default setting the LLDP and SNMP functions are disabled on the device. To have Industrial HiVision discover and display these devices, enable the LLDP and SNMP functions.
  - DAP847: In the default setting the LLDP and SNMP functions are disabled are disabled on the device. To have Industrial HiVision discover and display these devices, enable the LLDP and SNMP functions. Additionally, the Wifi connection are not displayed by the Auto-Topology function.

### 相关内容

- [ihivision08500\\_windows.exe.download.zip](#)

- [ihivision08500\\_linux.tar.download.zip](#)
- [HAC\\_Issue-List\\_2024-03-07.pdf](#)