

HiOS v07.1.00 released

2019-12-17 - Christoph Strauss - Switches and Router

Software Release 07.1.00

Bugfixes (see Issue List)

New Functions:

- Password change on first login

Protocols that require a login (e.g. SNMPv3) remain deactivated until the password is changed.

Related Content

- [HAC_Issue-List_2019-12-17.pdf](#)
- [Web_EES_07100.zip](#)
- [Web_EESX_07100.zip](#)
- [Web_GRS_07100.zip](#)
- [Web_MSP_07100.zip](#)
- [Web_OCTOPUS_07100.zip](#)
- [Web_RDD_07100.zip](#)
- [Web_RED_07100.zip](#)
- [Web_RSP-2A_3S_07100.zip](#)
- [Web_RSP-2S_07100.zip](#)
- [Web_RSPE_07100.zip](#)
- [Web_RSPL_07100.zip](#)
- [Web_RSPS_07100.zip](#)