



Base de connaissances > Products > Classic Switches > Are Hirschmann Classic switches and routers affected by the vulnerabilities described in CVE-2017-13077, -13078, - 13079, -13080, -13081, -13082, -13084, -13086, -13087, -13088?

---

Are Hirschmann Classic switches and routers affected by the vulnerabilities described in CVE-2017-13077, -13078, -13079, -13080, -13081, -13082, -13084, -13086, -13087, -13088?

- 2018-02-21 - Classic Switches

Hirschmann Classic devices are NOT affected by the vulnerabilities described in CVE-2017-13077, -13078, - 13079, -13080, -13081, -13082, -13084, -13086, -13087, -13088.