

Base de connaissances > Products > HiOS > Are Hirschmann HiOS devices affected by the vulnerabilities described in CVE-2017-13077, -13078, -13079, -13080, -13081, -13082, -13084, -13086, -13087, -13088?

---

Are Hirschmann HiOS devices affected by the vulnerabilities described in CVE-2017-13077, -13078, -13079, -13080, -13081, -13082, -13084, -13086, -13087, -13088?

- 2018-02-09 - HiOS

Hirschmann HiOS devices are NOT affected by the vulnerabilities described in CVE-2017-13077, -13078, -13079, -13080, -13081, -13082, -13084, -13086, -13087, -13088.