



Knowledge base > Products > Are Emerson branded Hirschmann products affected by the vulnerabilities described as ICMP Unreachable DoS Attacks (aka "Black Nurse")?

Are Emerson branded Hirschmann products affected by the vulnerabilities described as ICMP Unreachable DoS Attacks (aka "Black Nurse")?

- 2024-09-19 - Products

Emerson branded Hirschmann products are not affected by the vulnerabilities described as ICMP Unreachable DoS Attacks (aka "Black Nurse"), because ICMP type 3, code 3 packets cause no higher CPU load than other packets handled by the CPU.