

Knowledge base > Products > Are Schneider branded Hirschmann products affected by the vulnerabilities described in CVE-2017-3733?

Are Schneider branded Hirschmann products affected by the vulnerabilities described in CVE-2017-3733?

- 2024-09-19 - Products

Schneider branded Hirschmann products are not affected by the vulnerabilities described in CVE-2017-3733, because OpenSSL version 1.1.0 is not used.