

Are Emerson branded Hirschmann products affected by the vulnerabilities described as ICMP Unreachable DoS Attacks (aka "Black Nurse")?

- 2024-09-19 - Products

Emerson branded Hirschmann products are not affected by the vulnerabilities described as ICMP Unreachable DoS Attacks (aka "Black Nurse"), because ICMP type 3, code 3 packets cause no higher CPU load than other packets handled by the CPU.