

## HiLCOS 10.12 Release Update 11

2023-06-27 - - Wireless

**BELDEN**

### HiLCOS WLAN Software for BAT Devices

Combines Leading Wireless  
Security and Performance

**HiLCOS**   
The Hirschmann™ BAT Operating System



SHA-256 Checksum for download:

7824593f2dc0dfd190fc71b698628a5726a65c5ef6ecfc9a09a5f9044dd4b04a

## Improvements in HiLCOS 10.12.7153-RU11

### General

- Firewall for IPv4 enabled by default
- Default value of TCP max connection has been updated to 200 for all BAT device except WLC
- SSH Weak Key algorithms (SHA1-based) is disabled by default.

### Bugfixes

- Fixed DHCP IP addresses assignment over WLAN interface
- Improved BAT867 radio stability.
- Fixed roaming times when using WPA enterprise security for AccessPoints after reboots.

- Fixed issue that Reset-Config button was not active on Web-Interface
- Fixed issue in GPS position output for BAT450-LTE devices

Gerelateerde inhoud

- [HiLCOS 10.12.7153 \(Release Update 11\)](#)