

## HiOS 08.7.04 released

2021-11-22 - Christoph Strauss - Switches and Router

Bugfix for SFP issue, see <https://hirschmann-support.belden.com/news/posts/119>

Software Release 08.7.04

-----

Bugfixes (see Issue List)

### Gerelateerde inhoud

- [Web\\_BRS\\_08704.zip](#)
- [Web\\_DRAGON\\_08704.zip](#)
- [Web\\_GRS\\_08704.zip](#)
- [Web\\_MSP\\_08704.zip](#)
- [Web\\_OCTOPUS\\_08704.zip](#)
- [Web\\_RDD\\_08704.zip](#)
- [Web\\_RSP-2A\\_3S\\_08704.zip](#)
- [Web\\_RSPE\\_08704.zip](#)
- [HAC\\_Issue-List\\_2021-11-24.pdf](#)