

Notícias > Software Products > HiFusion v03.1.00 released

HiFusion v03.1.00 released

2017-12-05 - - Software Products

New features in version 03.1.00

• Generates PSMs compatible with Ind. HiVision 07.1.00.

Fixes in version 03.1.00

• The feature 'GPS Coordinates of a device' can be disabled, but property always appears in Ind. HiVision.

Fix: Feature cannot be disabled any more.

- If in one PSM different device icons were defined for different Sys OIDs it could happen, that all devices got the same icon. Fixed.
- Management protocols: The 2 checkboxes 'HTTP' and 'HTTPS' were replaced by the checkbox 'Web Interface'.

Ind. HiVision determines which version to use.

• The feature 'Signaling' was present in HiFusion. Only Hirschmann devices support Signaling.

Fix: Feature was removed from HiFusion.

Conteúdo Relacionado

- <u>HAC_Issue-List_2017-11-30.pdf</u>
- hifusion03100_linux.zip
- hifusion03100_windows.zip