



Base de Conhecimentos > Products > Are Schneider branded Hirschmann products affected by the vulnerabilities described in ICSA-15-169-01?

Are Schneider branded Hirschmann products affected by the vulnerabilities described in ICSA-15-169-01?

- 2024-09-19 - Products

Schneider branded Hirschmann products are NOT affected by the VxWorks TCP initial sequence vulnerability described in ICSA-15-169-01.