

Notícias > Wireless > HiLCOS 10.34 Release Update 3

HiLCOS 10.34 Release Update 3

2022-12-14 - - Wireless



Hirschmann is proud to announce the release of HiLCOS 10.34 Release Update 3:

https://hirschmann-support.belden.com/downloads/files/3754

For the devices:

- OpenBAT (BAT-F and BAT-R)
- BAT450-F (all variants, except LTE)
- BAT867-R and BAT867-F
- BAT Controller Virtual and BAT WLC

Download also contains complementary software LANConfig and LANMonitor

Feature highlights as of version 10.34.5725 (Release Update 3)

Full list of new features can be found in the release notes in the zip file.

• Easy WLAN diagnostics function, so all data can be downloaded in one simple file. A Demo and How-To guide is available as well:

https://hirschmann-support.belden.com/kb/articles/1304

Bugfix highlights as of version 10.34.5725 (Release Update 3) Full list of bugfixes can be found in the release notes in the zip file.

- Security updates
- Singapore: U-NII-3 channels are now supported
- Improved Client support when connected to Huawei Access Points

Tags			
10.34			
BAT			
CSV			
Diagnostics			
firmware			
HiLCOS			
HiLCOS 10.34			
LANConfig			
LANTools			
WiFi			
WLAN			
WLANConfig			

Conteúdo relacionado

- WLAN Diagnostics
- HiLCOS-10.34.5725-RU3.zip