

HiOS 09.0.00 released

2022-01-04 - - Switches and Router

Software Release 09.0.00

Bugfixes (see Issue List)

New Functions:

- Responsive GUI
- Profinet Stack update BRS, OS8TX
- Double VLAN Tagging RSP, RSPE, GRS1040, GRS106, MSP40, Octopus2 and Octopus 3

Conteúdo relacionado

- [Web_BRS_09000.zip](#)
- [Web_DRAGON_09000.zip](#)
- [Web_GRS_09000.zip](#)
- [Web_MSP_09000.zip](#)
- [Web_OCTOPUS_09000.zip](#)
- [Web_RDD_09000.zip](#)
- [Web_RSP-2A_3S_09000.zip](#)
- [Web_RSPE_09000.zip](#)
- [HAC_Issue-List_2021-12-21.pdf](#)