

HiOS 09.2.00 released

2023-03-30 - - Switches and Router

Software Release 09.2.00

Bugfixes (see Issue List)

New Functions:

- Signed Firmware Images
- SNMPv3 Traps

Software Level 2A:

- SNMPv1/v2 Read-Only
- Interface Shutdown via Tracking

Conteúdo relacionado

- [HAC_Issue-List_2023-03-24.pdf](#)
- [Web_BRS_09200.zip](#)
- [Web_GRS_09200.zip](#)
- [Web_MSP_09200.zip](#)
- [Web_OCTOPUS_09200.zip](#)
- [Web_RSP_09200.zip](#)
- [Web_RSPE_09200.zip](#)
- [Withdraw of HiOS SW version 09.1.00 and higher for RSP, OS2 und RSPE](#)