

## HiOS 09.2.00 released

2023-03-30 - - Switches and Router

Software Release 09.2.00

-----

Bugfixes (see Issue List)

New Functions:

- Signed Firmware Images
- SNMPv3 Traps

Software Level 2A:

- SNMPv1/v2 Read-Only
- Interface Shutdown via Tracking

Conteúdo relacionado

- [HAC\\_Issue-List\\_2023-03-24.pdf](#)
- [Web\\_BRS\\_09200.zip](#)
- [Web\\_GRS\\_09200.zip](#)
- [Web\\_MSP\\_09200.zip](#)
- [Web\\_OCTOPUS\\_09200.zip](#)
- [Web\\_RSP\\_09200.zip](#)
- [Web\\_RSPE\\_09200.zip](#)
- [Withdraw of HiOS SW version 09.1.00 and higher for RSP, OS2 und RSPE](#)