

## HiOS 10.2.00 has been released

2024-12-19 - - Switches and Router

Software Release 10.2.00

-----

Bugfixes (see Issue List)

New Functions:

Software Level 2A:

- TACACS+ client

- sFlow

Conteúdo relacionado

- [Web\\_BRS\\_10200](#)
- [Web\\_GRS\\_10200](#)
- [HAC\\_Issue\\_List\\_2024-12-19](#)