

## Classic Switch v09.0.18 released (MACH1040 and MACH 104)

2019-05-20 - - Switches and Router

Classic Switch software 09.0.18 has been released for MACH 1040 and 104.

This version fixes a link issue in combination with SFPs:

In certain scenarios when unplugging a fiber link from a port also the neighbor port is going down

### 相关内容

- [Web\\_MACH100GE\\_09018.zip](#)
- [Web\\_MACH1000GE\\_09018.zip](#)
- [HAC\\_Issue-List\\_2019-05-17.pdf](#)